ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
5

Ward Name
Jakkuru

Street ID
W0398, W0749, W0396, W0400, W0402, W0404, W0406, W

Street Name
4th Crs, NA, Narayanaswamy Rd 4th Crs

Significant Landmark
KOGILU LAYOUT

Segment No.
5/C-W0398/S123105

Total Length (m)
381.61

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	130.75	77.632984	13.102064	77.632779	13.100899	M0016	DEAD END
2	73.19	77.631270	13.107153	77.631085	13.106517	W0398	W0408
3	45.68	77.631137	13.106627	77.631539	13.106507	W0749	DEAD END
4	44.21	77.631198	13.106824	77.631585	13.106697	W0749	DEAD END
5	44.46	77.631241	13.106991	77.631624	13.106849	W0749	DEAD END
6	43.32	77.631283	13.107127	77.631660	13.106998	W0749	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to roads and drains at kogilu layout ward no 5 byatarayanapura sub-division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1500000

Sanctioned Year
2015

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to roads and drains at kogilu layout ward no 5 byatarayanapura sub-division Yelahanka zone

Job No. / Work Code
005-15-000011

Work Order No.
EE/BTP/BBMP/E-PMT/110/2015-16

Work Order Date
26/10/2015

Period of Extention
60

Defect Liability Period From
26/10/2015

Defect Liability Period To
25/10/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)

B.VENUGOPAL REDDY 0.00

Phone No. **E-Mail ID**

8892916565

Field Inspection Details

Number of Trees

6

Any Other Information

Name

chandrakanth

Date of Inspection

30/05/2016

Remarks

completed

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0398, W0749, W0396, W0400,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	30/05/2016	29/06/2016	COMPLETED
SE	VASU K.M	30/05/2016	29/06/2016	COMPLETED
EE	YARAPPA REDDY	30/05/2016	29/06/2016	COMPLETED
AEE	J.N. LOKESH	30/05/2016	29/06/2016	COMPLETED
AE	CHANDRAKANTH	30/05/2016	29/06/2016	COMPLETED
AE	CHANDRAKANTH	30/05/2016	29/06/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0398, W0749, W0396, W0400,